

IMPORTANT OWNER'S INSTRUCTIONS

IMPORTANT INSTRUCTIONS FOR YOUR NEW INTEGRATED POWER SYSTEM (MS)

Congratulations on your purchase of your AKUMA motorcycle helmet. Akuma helmets feature the latest in technological innovation and technology for helmets.

To charge your helmet, locate the small recharge plug under the cheek pad between the bottom liner and plug it into the wall charger. Plug the wall charger into a U.S. rated socket for no more than 2 hours. After charging, unplug the helmet from the wall charger and tuck the recharge plug back under the cheek pad.

CAUTION

In order to keep your helmet system functioning as designed and in good condition, please observe the following recommendations:

- » To charge your helmet, locate the small Red recharge plug under the cheek pad between the bottom liner and plug it into a wall charger. Plug the wall charger into a U.S. rated socket for no more than 2 hours. After charging, unplug the helmet from the wall charger and tuck the recharge plug back under the cheek pad.
- » Do not immerse in water.
- » Do not charge the Integrated Power System while wearing the helmet.
- » Do not insert objects into the charging port.
- » Do not disassemble or attempt to repair the helmet Integrated Power System
- » If the system give off any unfamiliar odors of if there is any smoke, please return the helmet to the manufacturer for a full replacement.
- » Do not charge the Integrated Power System with any other charger except the charger provided with the helmet.
- » Do not leave the helmet in a hot car or any other environment where the temperature could exceed 150 F
- » Do not charge the helmet for longer than necessary. Charging requires a maximum of 2 hours.
- » Do not operate the LEDs with the system charging.