

SUNSHIFT™ VISOR USER'S MANUAL

To keep your Sunshift™ visor functioning properly and in good working condition, please follow these suggestions and instructions.

- » Clean the Sunshift™ visor with a soft cloth, mild soap and water
- » Do not use harsh abrasive cleaners or detergent to clean the visor
- » Do not leave the Visor in direct sunlight when not in use as this will degrade the visor's service life.
- » Visor contains an abrasion resistant anti-fog coating on the inside. To refresh the coating, submerge the visor in cold water for approximately 5 Minutes.

CAUTION

When entering a tunnel or low light area, treat the Sunshift™ visor as you would a normally tinted or iridium visor or sunglasses. Lift the visor before entering or stop until your eyes are adjusted. It takes approximately 30 seconds to 1.5 minutes for the visor to tint from clear to smoke and several minutes to tint from smoke to clear when removed from direct sunlight.